

0855Z 20 JAN 63

S E C R E T

25X1 DIRECTOR

[REDACTED]

OSA (1,2,3,4,5,6,7,8,9,10,11,12,13,14,15,16)

S/C (17)

TOR 1125Z 20 JAN 63

PRIORITY

25X1 IN 63109

25X1 PRITY [REDACTED]

NO NITE ACTION

25X1 [REDACTED]

25X1 1. [REDACTED] POST FLIGHT FINDINGS MISSION

3213/190140/342.

25X1 2. [REDACTED] "X" AND "S" BANDS MASTER RECORDER, OPERATED WITH ONE AND LESS THAN TWO DBM TRANSSSENTUAL. NOISE, SATURATION AND VOLTS REMAIN THE SAME.

25X1 3. [REDACTED] "L" AND "P" BAND SLAVE RECORDER, NO CHANGE THAT WHAT HAS BEEN REPORTED ON PRE-FLIGHT DATA SHEET WITH TAPES SENT HQS.

25X1 4. [REDACTED], OPERATED WELL THROUGH OUT MISSION.

5. ALL RECORDERS, TONES ON RECORDERS, AND SWITCHING TIMES OPERATED PROPERLY.

25X1 6. UNABLE TO DETERMINE REASON FOR NO SIGNALS ON [REDACTED]

25X1 [REDACTED] PLAN TO RUN TEST HOP ASAP.

END OF MESSAGE

S E C R E T

25 YEAR RE-REVIEW

REPRODUCTION BY OTHER THAN THE ISSUING OFFICE IS PROHIBITED.

Copy 115